

READING LIBRARY

SOLICITATION F09603-01-R-70306

P-23 HUB ASSEMBLY REPORTS/ OTHER DOCUMENTS FURNISHED WITH THE SOLICITATION:

- 1- Report - Failure Analysis of P-23 Fire Truck Wheel Assembly Stub Axle from Cape Canaveral AS FL
- 2- Report - Failure Analysis of P-23 Fire Truck Wheel Assembly Stub Axle from Seymour Johnson AFB NC
- 3- Report - Failure Analysis of P-23 Fire Truck Wheel Assembly Stub Axle from Anderson AFB GU
- 4- Report - Failure Analysis of P-23 Fire Truck Wheel Assembly Stub Axle from Travis AFB CA
- 5- Letter - Report - Failure Analysis of P-23 Fire Truck Wheel Assembly Stub Axle, 13 Jul 98
- 6- Report - Failure Analysis of P-23 Fire Truck Wheel Assembly Hub Housing from Seymour Johnson AFB NC
- 7- Letter - Report - Failure Analysis of P-23 Fire Truck Wheel Assembly Stub Axle, 12 Jun 98
- 8- Report - Failure Analysis of P-23 Fire Truck Wheel Assembly Hub Housing from Holloman AFB NM
- 9- Report - Failure Analysis of P-23 Fire Truck Wheel Assembly Hub Housing from Mildenhall AB UK
- 10- WR-ALC/TIEDM, Failure Analysis of P-23 Fire Truck Wheel Assembly Hub Housing Report Number 98-MFA-062
- 11- WR-ALC/TIEDM, Structural Analysis Report Number DTA-TR-98-004
- 12- Battelle Phase I Data on Axle 3
- 13- Battelle Final Report Files on Phases I and II
- 14- Battelle Axle 1 Time Series Data File
- 15- Battelle Axles 2 & 4 Time Series Data File
- 16- Battelle Axle 1 Results File
- 17- Battelle Axle 2 Results File
- 18- Battelle Axle 4 Results File

All of the above are provided with the solicitation via a link on the website.